




Measuring Guide

Window Blinds

1. Don't use cloth tape. Use Steel Measuring Tape.
2. Take & record window measurements in inches
3. First Record Width Then Height or Drop
4. Mention Window Location, Number of Windows & Shape. For Example, = Bedroom, 2 Windows, Rectangular, Square, L Shape, Arch or bay window.
5. Measure each window separately even it looks same.
6. Maximum Width of 7 - 8 feet is feasible to install in one piece
7. Windows larger than 9 feet would be install in two pieces
8. Division or Bracket gap will come between 2 blinds.
9. Take Width (from left to right) Then Height or drop (top to bottom)




Recess Measurements / Inside Window Installation

Check Window Depth




- Minimum depth required (2.50 Inches) or more
- Measure Inside window width and inside height
- Don't make any deductions. We will deduct for proper functioning.


Inside Width



Inside Height




Above Measurements / Above Window Installation



- Take Width (from left to right) then Height or drop (top to bottom)
- Add 4 inches overlap in both sides of width & height
- Total overlap Should be 8 Inches in Width and Height.

Corner Window Measurements / L Shape Window



- First you have to decide which blind will be installed in full & which blind will take the gap. Choose from option above
- We recommend full blind should be for main window where you need the most privacy
- Decide You want to mount above the window or inside window as described above & Take Measurements Accordingly.
- Don't deduct from measurements. Mention you how you take the sizes & what's your installation type above or inside window

Wall Aesthetics

Window Blinds Shop

Contact 03228015567

Website <https://wallaesthetics.com/>

Shop # 18 Al-Hafeez Tower, Ground Floor, Gulberg III, Ghalib Road, Lahore